



## FOR SAFE WORKING LIVES

FIELD ID ELECTRONIC INSPECTION SYSTEM













# FIELD ID **LIFTING ASSETS**

Field ID is the world's leading paperless safety compliance and equipment inspection system. The system web-based technologies with the power of mobile devices to improve the efficiency, reliability and reporting of workplace safety management. Robertsons Inspectors use Field ID to improve the accuracy of equipment inspections and enable you to access and manage your assets easily.

### The Lifting & Height Safety Asset Management Cycle



## SAFETY **MADE SIMPLE**

Being a fully compatible electronic system, Field ID makes equipment compliance and keeping track of your lifting and rigging assets simple.

## Field ID

- ✓ Increases workplace safety
- Increases inspection and audit efficiency, reducing your liability
- ✓ and in turn, saves you money.

By eliminating inspection and audit paperwork our LEEA trained inspectors will conduct inspections and audits faster and more securely (using iPad's) and upload your reports almost instantly.

This enables you to access reports, certificates and your asset management database through the easy to use and navigate, Field ID Asset Management System - either from your PC or your own smart technology devices.








Product Code: Z-0855G10020L

#### Chain Sling G100 2 Leg c/w Shortening and Self Locking Ho



## **CHOOSE YOUR SAFETY TAG SYSTEM OPTION**

## **Option 1: The RGBY System**

In line with standard mining and construction procedures, the colour coded RGBY (Red, Green, Blue, Yellow) maintenance system allows for easy referencing and safety procedures. The RGBY system is commonly used for quarterly inspections. Each tag contains the most recent inspection date, and the colour should correlate with the quarterly colour indicated on the inspection board. A yellow 'Out Of Service' sticker is placed on any equipment which has failed the inspection.



## FIELD ID **CAPABILITIES**

## **Scheduling Functionality**

Utilising the Field ID system, we can effectively managed the entire inspection scheduling process so you don't have to worry. If you wish to track when an inspection or audit is due, the information is easily available in an extremely user-friendly format.

	BUNZL safety						Welcome, Zoe Birch Support	Sion Out   Saved Items 🔻		
Rew Asset Start Event Search Reporting w Setup w Search										
0 0 58	Advanced Search	selected. <u>Select all 240 ib</u>	ems or <u>Clear selection</u>						Email Save	
Г	Customer Name	ID Number	Asset Type V	Asset Status	Location	Date Identified	Last Event Date	Next Scheduled Date		
	ABC Customer	6473	Chain Sling	Inspection Pending		03/12/2013	05/12/2013 7:32 AM EST	01/03/2014	Actions -	
	ABC Customer	97223	Chain Sling	Inspection Pending		03/12/2013	04/12/2013 9:25 AM EST	01/03/2014	Actions -	
	ABC Customer	<u>B6437</u>	Chain Sling	Inspection Pending		03/12/2013		01/03/2014	Actions -	
	ABC Customer	BB24313	Chain Sling	Inspection Pending		03/12/2013	05/12/2013 7:28 AM EST	01/03/2014	Actions -	
П	ABC Customer	BS4006100-2	Chain Sling	Inspection Pending		03/12/2013		01/03/2014	Actions -	
	ABC Customer	<u>D20</u>	Chain Sling	Inspection Pending		03/12/2013	05/12/2013 8:31 AM EST	01/03/2014	Actions -	
	ABC Customer	<u>D6469</u>	Chain Sling	Inspection Pending		03/12/2013	05/12/2013 7:45 AM EST	01/03/2014	Actions -	
	ABC Customer	<u>D6470</u>	Chain Sling	Inspection Pending		03/12/2013		01/03/2014	Actions -	

### **Full Asset Management**

Field ID offers simplified organisation and access to your lifting and height safety assets. There are multiple data and filtering functions which makes finding detailed information about particular assets easy.

### **GPS** Capabilities

With Field ID's GPS capabilities, you can see exactly when and where an inspection or audit was performed. This information is also stored for future reference.





#### **Detailed Asset Information Screen**

safety			Welcome, Zoe Brich	Support Sen Out	I Smediterra 👻
New Asse				Search	
Chain Sling /	M6831 / In Servic				
And the onling of	110002 / 111 001110				
Summary Events				Edit Sched	ule Start Event
		Schedules			
	Ă	Chain Sling Visual In 161 Days on 24/04/2014			Stort -
	Λ	Last Event Performed			
	$\Lambda$	24/10/2013 3:03 PH EST Date Completed	Chain Sling Visual Event Completed	Jason Heppes Performed By	View +
•		Attachments			
	Map -	No attachments for this asset.			
LL + bat + He	тыля	More			
S- MY	Whard Smith NEW	Warnings			
0	Merthyr •	Add Your own Warnings, or remove this de	fault		
GOUNE Mag	data @2013 Opogle Terms of Use	Hore Information			
Details		-Add your own instructions, or remove this o	default		
Assigned To	Unassigned	Comments			
Description	f/w Headrings each end				
Diameter	26mm				
Leg/s	1				

## **EASILY ACCESS & SHARE REPORTS**

Field ID puts all your inspections and audits in the one place, enabling you to access your safety data in real time - 24 hours a day, 7 days a week. Customers can also access and share asset reports and information from their own iPad or iPhone. Suddenly, safety success is not only possible, it's simple and easy!

tal the tyle mode hits					0		P WALLER	And the Party of t	arte. a Sup	nav31.4681.	
Cobertsons				un later 1	-	AL 1 1990		and Soberts	75		- 10
A new Asset Start Lawy So	ach = Reporting = Safe	-			_			Chain Sing / N6232	_	inud a line a	- 11
Event Summary Report								(Secol (secol)			
Events Due Comp	and Ore		cloring	Fand		net	0			-	
259 25	59 0		0	251		8		Ă		-	
Detailed Breakdown							- 1				-
Assel7pes Dart7pes OalyDeal	down.	Set be	Completed	Greet	<b>Outprolog</b>	Passed	144			Contract Contract	
Nobel Stap / Te Off Adapter		3	3		0	3		1 20	-		
Dan Birk		3	3			3			-	and the second second	- 9-
than sing		26	28			26	•			the Manufactor	
Tare Malbas		1								-Correction	
M Anat Davis										Canada	
while Device		2	1		•				-		9-
all Dence		1	1		•	4			-		2-

### Reporting

Field ID's various reports assist customers with the sometimes arduous task of remaining compliant with safety regulations. The simplified search and reporting functions of the system also help you to gain insight into maintaining the safest workplace.

Visual Inspection Reports, which show whether individual items have passed or failed on a specific date can be easily downloaded in PDF format.

Full summaries of an inspection can also be viewed in the Event Summary Report.

#### Inspection Event Summary Report

New Asset Start Eve	nt Search <del>-</del> Repo	ting 👻 Setup 👻				Search		
Event Summary Report								
Events Due	Completed	Closed	Out	standing	Pas	sed	Falled	0
259	259	0		0	25	<b>51</b>	<b>8</b> (3.1%)	
Detailed Breakdown								
Asset Types Event Types Da	ily Breakdown		Events Due	Completed	Closed	Outstanding	Passed	Failed
Anchor Strap / Tie Off Adapter			3	3	0	0	3	0
			3	3	0	0	3	0
Chain Block			5					
			36	36	0	0	36	0
Chain Sling					0	0	36 1	0
Chain Sling Crane Workbox			36	36				
Chain Sing Crane Workbox Fall Arrest Device			36 1	36 1	0	0	1	0
Chan Block Chan Slog Crane Workbox Fall Arrest: Device FarkAft: Device Harness Fall Arrest			36 1 1	36 1 1	0	0	1	0

#### **Inspection Report Certificate**

		IS Nos		E: inspections@	ng.com.au gir.com.au 20 977 577 LEEA
		Visual Insp	pectio	n Report	
Page: 1 of 1			Insp	ection Result: Pass	
Customer: ABC C	ustomer		Divis	ion:	
Address: 123 Jo	nes ST		Loca	tion:	
	ne Qld 4000		Phor		
	97223			rence #:	
Equipment Type:	Chain Sling		Orde	r#:	
Asset Status:	In Service		Insp	ected On: 07/11/2013	
	Chain Sling	- Marke and		Chain Sling (continue	d) Status
Description:	f/w Shortenin Self Locking	Hooks		Description	otatus
Diameter:	10mm		13	Elongation and wear on components	Pass
Leg/s:	2		14	Corrosion or Pitting or Weld	Pass
Grade:	80			Splatter Wear at load bearing points	Pass
Length:	5M			Wear at load bearing points Excessive play of load pin	Pass
Working Load Limit:	5.5t			ortening Hooks	1 435
Angle:	60 Degrees		17	Identification of Grade	Pass
Last Proof Load Date:	3/12		18	Manufacturer, Batch Components Bent, Twisted or Siezed	Pass
Manufacturer:	Robertsons		18	Elongation and wear on components	Pass
				of more than 10% Corrosion or Pitting or Weld	
# Description		Status	20	Splatter	Pass
Tag		ouno	Cha		
1 Identification of Serial	Number	Pass	21	Manufacturer, Batch	Pass
2 Identification of Grade	i	Pass	22	Chain Bent or Twisted Elongation and wear of chain of	Pass
3 Identification of Manuf		Pass	23	more than 10%	Pass
4 WLL correct for Config		Pass	24	Corrosion or Pitting or Weld Splatter	Pass
5 Tag Damaged or Illeg	ible	Pass	25	Nicks or Cracks	Pass
Headring Identification of Grade			Bot	tom Hooks or Fittings	
Manufacturer, Batch		Pass	26	Identification of Grade, Manufacturer, Batch	Pass
7 Components Bent or		Pass	27	Safety Latch Worn or Damaged	Pass
8 Elongation and wear of of more than 10%	on components	Pass	28	Excessive play of clevis pin	Pass
9 Corrosion or Pitting		Pass	29	Components Bent, Twisted or Siezed	Pass
10 Weld Splatter		Pass	30	Elongation and wear on components of more than 10%	Pass
Connectors 11 Identification of Grade			31	Corrosion or Pitting or Weld Solatter	Pass
Manufacturer, Batch	istad or Siavad	Pass Pass			
i <u>Son Out</u> i Saved B	****		compression	ial inspection of this equipment with the sequence of the safe care ment remains the ultimate res / operator.	ras completed by a and use of this ponsibility of the
Falled 8 (3.1%)	ê				
tanding Passed	Failed 0				
3	0				
36	0				
30	U				

## ACCESSING YOUR **ASSET REPORTS & INFORMATION**

### Asset Summaries

An Asset Summary Report enables you to conveniently view a summary of all your equipment to determine if these assets are bing inspected and maintained in a safe and serviceable condition.

Hand information such as the product description and manufacturer, as well as the date of result of any inspection performed, are available on the one screen.

BUNZL	
safety	testing <sup>^</sup> technical <sup>^</sup> services

#### **Asset Summary Report**

tomer Name:	ABC Company
sion:	Rigging

Cus

Division:	Rigging										
Date Performed	ID Number, Reference Number	Asset Type	Asset Description	Description	Length	Manufactureer	WLL	Location	Asset Status	Event Type	Result
04/11/2013	0022	Flat Webbing Sling		Yellow	1m	Beaver	3t	Workshop	Out of Service	Synthetic Webbing Sling Visual	Fail
04/11/2013	0019	Flat Webbing Sling		Yellow	1m	Beaver	3t	Crane 1	In Service	Synthetic Webbing Sling Visual	Pass
04/11/2013	64-152	Girder Trolley	Girder - Push	Proof Load 7.35kN		PWB	500kg	Crane 1	In Service	Trolley Visual Inspection	Pass
04/11/2013	Oio 16	Air Hoist				Toku		Rigging Loft	In Service	Trolley Visual Inspection	Pass
04/11/2013	091b	Chain Sling	7mm Gr 80	f/w Safety Hooks	2m	Robertsons	2.8t	Workshop	Out of Service	Chain Sling Visual	Fail
04/11/2013	738u	Chain Sling	7mm, Gr 80	Shortening Hook	4M	Robertsons	1.6t	Crane 1	In Service	Chain sling Visual	Pass
04/11/2013	a18	Shackle	Bow Screw Pin Gr S			Beaver	3.2t	Rigging Loft	In Service	Shackle Visual	Pass
04/11/2013	A16	Shackle	Bow Screw Pin Gr S			Beaver	3.2t	Rigging Loft	In Service	Shackle Visual	Pass
04/11/2013	A06	Shackle	Bow Screw Pin Gr S			Beaver	3.2t	Rigging Loft	In Service	Shackle Visual	Pass
04/11/2013	A06	Shackle	Bow Screw Pin Gr S			Beaver	3.2t	Rigging Loft	In Service	Shackle Visual	Pass
04/11/2013	J2769	Chain Sling	8mm, Gr 80	f/w Safety Hooks	2M	safety	et Start Event	Search w Reporting w Se	tup w	Welcome, <u>Zoe Birch</u>   Sugar Seat	_
04/11/2013	D7145	Chain Sling	10mm, Gr 80	f/w Shortening Hooks and Safety Hooks	3020mm	Chain Sling , Summary Event		Service			idit Schedule

More detailed information can also be accessed from the Asset Summary Report screen.

P: 1300 977 577 LEEA



New Asset				Search
ain Sling / M	6831 / In Servio	e		
ummary Events				Edit Schedule StatEver
		Schedules		
	A	Chain Sling Visual In 161 Days on 24/04/2014		Start +
	4	Last Event Performed		
1	1	24/10/2013 3:03 PM EST Date Completed	Chain Sling Visual Event Completed	Jason Heppes Performed By View *
•	•	Attachments		
Sa anno	Map *	No attachments for this asset.		
Seal De	AV11XX	More		
LL Sat * hal • Howse 3 = are •	d Smith NEW	Warnings		
9	Whatves Plants Merthyr Village	Add Your own Warnings, or remove this default-		
Cagelie Map day	a @2013 Google Terms of Use	Hore Information		
Details		-Add your own instructions, or remove this defau	<i>d</i> t	
	Unassigned			

## STEPS TO ACCESS YOUR ASSET REPORTS & INFORMATION

		BUN	ty	Roberts testing^techr	ical Aservices			Inspectio login and	on Logi d passv	n icon an vord. You	id log in to ir dashbo	o Field ID ard is you graphs a	o <b>m.au</b> clock on O with your unio ur own home p and statistics.	que
		1	1				🚖 Search 🛩	Reporting					Search	
		â	password				Dashboard / Customer Demonstration						Widgets Dashboa	irds
			Remember Me				Welcome. G	et Started v	vith t <mark>h</mark> e Sa	afety Dashb	oard in 3 Sim	ple Steps:		
			Logn	Forgot your Pas	sword?			1		6	3		3	
			Request an Accor	nt			- Ad	d More -	÷	- dh	)		4	
	(i) This website is p	rotected by <u>256-b</u>	it SSL security		@ 2007 - 2012, h	4 Systems Inc	Add widget	s to your Dashboard f Add More list	rom the	Click, hold and drag v	vidgets to move them	Customize ea	sch widget by clicking on the onfiguration icon	
							2013.7.2						POWERED BY	
Step 2: 3 like to via Step 3: 1 informati	ew. √iew a	nd dov	wnload			•	Res of the sector of the secto		Run a sea Tips: • Clck Columns • Clck the X in	seema v Sete -	layout its full width	Search	an Anala in a star <u>Bannan hasid</u>	L Email
	New Asset Start	Event Search <del>-</del>	Reporting 🛩 Setu	¢ ~	Welcome, <u>Jan Birch</u> Second Search	Son Dat 1 Start	of Tons v			0		Wheel Dozer: Fixed	Download the <b>Field ID App</b> to gain access	)
Customer Name	ID Number	Asset Type	✓ Asset Status	Location Date Ide		Next Scheduled		F	ELDiD		Summary Serial Number		anywhere,	
ABC Customer	62368	Chain Sing Chain Sing	Inspection Pending	06/11/201 06/11/201		07/02/2014	Actions +	Company	Name		851D Number Asset Status		anytime!	
ABC Customer	02269	Chain Sing	Inspection Pending	06/11/201		07/02/2014	Actions +	Password	OFF	Start Event Edit	Identified Assigned To			
ABC Customer     ABC Customer	66432	Chain Sing	Inspection Pending	06/11/201		07/02/2014	Actions +	Passion	Login	formed mance impection on 18/31/	Organization			
ABC Customer	61735/1	Chain Sing Chain Sing	Inspection Pending	06/11/201 06/11/201		07/02/2014	Actions +	Settings	to Field ID	d Beend mance Inspection on 11/38/	job Site Divisien			
ABC Customer	61235/2	Chain Sing	Inspection Pending	06/11/201	3 07/11/2013 8:30 AM EST	07/02/2014	Actions +	1 am new	w read to 3	12//-	Location Reference Number			
ABC Customer	97223	Chain Sing	Inspection Pending	06/11/201		07/02/2014	Actions +			and the same	Attributes			
ABC Oustomer     ABC Oustomer	2453845	Hook	Inspection Pending	06/11/201 06/11/201		07/02/2014	Actions +	-	6	optimal wheel doper for Bity, speed and compaction	Seats			
ABC Customer	SH51789	Hook	Inspection Pending	06/11/201		07/02/2014	Actions +					~		



**CONTACT US** 

▲ 1800 967 573
 △ info@bunzlsafety.com.au
 ④ bunzlsafety.com.au